


Al's DC welder



Switch – one position connects via 1 ohm resistor, middle position is OFF, second position no resistor